Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight — ***DHR Id#:*** **046-0064**

Resource Identification

Property Name(s): ..... Carroll Plantation {Historic}
Property Date: 1800
Address(s): .... Route 621 {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: . ...Virginia
USGS Quad Name: ..... BACONS CASTLE

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
other	other	Wood	other
other	other	Wood	other
Roof	Roof - Gable	Wood	other
Foundation	Foundation - Solid	Brick	other
Porch	other	Wood	Porch - Columns, Tuscan
Porch	Porch - 1-story, 7-bay	Wood	other
Roof	Roof - Gable	Metal	Roof - Standing Seam
Windows	Windows - Sash, double-hung	Wood	Windows - 9/9
Windows	Windows - Sash, double-hung	Wood	Windows - 9/6
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6
Windows	Windows - Sash, double-hung	Wood	Windows - 4/4
Windows	Windows - Fixed	Wood	other
Chimneys	Chimneys - Exterior end	Brick	other
Windows	Windows - Fixed	Wood	other
Structural System	Structural System - Frame	Wood	other

WUZIT Count:

No.	Wuzit Types	Historic?
1	Granary	Historic
1	Smoke/Meat House	Historic
1	Single Dwelling	Historic
1	Well	Historic
2	Archaeological Site	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0064**

Individual Resource Information

WUZIT: ..... Archaeological Site

Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: .....
Description: Architecture Summary: A dovecote and kitchen are identified in the site plan as being gone. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Well

Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: .....
Description: Architecture Summary: Compass brick well in site plan. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Granary

Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: .....
Description: Architecture Summary: Granary in site plan. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Smoke/Meat House

Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: .....
Description: Architecture Summary: Smokehouse in site plan. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Single Dwelling

Est. Date of Construction: .... 1800 ca {VDHR Survey File}
Accessed? ..... Yes
Primary Resource? ..... Yes
Number of Stories: 2.5
Architectural Style: ..... Federal
Condition: ..... Deteriorated
Interior Plan Type: ..... Side Passage, Double Pile
Threats to Resource: ..... Vacant
Description: Architecture Summary: Built in two sections not more than 15 years apart, the house is a fine example of Federal architecture. The house as it now exists is the fusion of two double pile sidehall plan structures built at almost the same time. Both parts of the building are extensively wainscotted with individual stairs and later mantles. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Architecture/Community Planning

Bibliographic Documentation

Ownership Information

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-0064**

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			1973/10/99	
B&W 35mm Photos	4234		1977/11/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ... ... Intensive Survey
Date: 1973/10/99
Organization or Person: ..... Bernard Herman
CRM Event Notes or Comments: .....

CRM Event # 2,
Cultural Resource Management Event: ..... Intensive Survey
Date: 1977/12/14
Organization or Person: ..... Dell Upton
CRM Event Notes or Comments: ....

VIRGINIA
HISTORIC LANDMARKS COMMISSION
SURVEY FORM

46-64
File Number

1. County Isle of Wight
   Town
   Street No. rt. 621

   USGS Quad Name Bacon's Castle, Va.
   Quad Date 1969
   Original Owner unknown
   Original Use dwelling
   Present Owner Mr. & Mrs. W.C. Wessels
   Present Owner Address Junkins Bridge, Va.
   (possibly the same Wessels who own Wessels root cellar)
   Present Use vacant

2. Historic Name Carroll Plantation
   Present Name House with Fanlights
   Date or Period (exact or estimate) circa 1800
   Architect
   Builder, craftsman, etc.
   Source of Name
   Source of Date construction

3. No. stories (dormers count as ½ story):
   2 & 1½
   Wall construction
   frame
   Acreage approx 8 acres

4. Historical Significance (Chain of Title, Families and Events, etc., connected with the property)

5. Architectural Significance (Note interesting interior and exterior details, etc., cite significant alterations and additions)

Built in two sections not more than 15 years apart, the House with Fanlights is a very fine example of Federal architecture. The house as it now exists is the fusion of two double pile sidehall plan structures built at almost the same time. Both parts of the building are extensively wainscoted with individual stairs and later mantels. The entire structure rests on a foundation and deep cellar laid in three course American bond with two end chmneys at either end also laid in three course American bond and having double stepped weatherings on the south end and triple weatherings on the north end.

Of particular interest is the two story block with a huge fanlight in the north end, a fully paneled stair way and fairly unique pedimented doorways consisting of pilasters rising from the base of the door frame and supporting a carved broken pediment enclosing a glass fan light. Of similar design but without the fanlight and supporting a full pediment is the doorway to the 1789 portion of the Todd House in Smithfield. The story and a half wing to the building has full wainscote in the western downstairs room, while the eastern room and hall have only a heavy chair rail. The stair located in the western end of the hall is enclosed except for the bottom few steps which support a simple rail on straight balusters.

6. Physical Condition

	Excellent	Good	Fair	Poor
Structure		X		
Grounds			X	
Neighborhood			X	

7. State potential threats to preservation of structure

Lack of interest in preservation.

(over)

8. List Number of Photographs _____Exterior _____Interior _____Outbuildings

9. Sources and Bibliography:
   A. Published Sources (author, title, date, page number, etc.)

   B. Primary Sources (original or later drawings, old photographs, pictures, manuscripts and their location)

   C. Names and Addresses of People Interviewed

10. Name, Address and Title of Recorder:

Bernard L. Herman/vhlc
Date of Record
October 1973

11. First Floor Plan (Rough Plan indicating arrangement of rooms, doorways, windows on ground floor)



12. Site Plan (Locate and identify outbuildings, dependencies, and significant farm structures)